
Discontinued: PB5922 Service Kit (Asco)

For PB5587 & PB5589 Air Cylinders (Asco)

Advisory

The *PB5922 service kit* for the PB5587 and PB5589 air cylinders is now **obsolete**.

Customers with the PB5587 or PB5589 air cylinders from Asco will no longer be able to repair these cylinders.

Updated cylinders are as follows:

Current Cylinder	Replacement Cylinder	Repair Kit for Replacement Cylinder
PB5587 (Asco)	PB33352 (DH)	PB33353
PB5589 (Asco)	PB33354 (DH)	PB33353

These cylinders are a direct replacement.



PB33352 Air Cylinder



PB33354 Air Cylinder



PB33353 Repair Kit